

Menu

HISTORY FILE MAP for year 2002


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

200.17.10-17.17: 7m real-time 1024bps data lost due to DSS-24 Stations Communications Processor (SCP-2) failure. SCP-2 swapped to SCP-1, telemetry was restored. DR G101407 refers.



198.21:15-21:20: 5m real-time 1024bps and 23m 512bps playback data lost due to DSS-15 (198.14:11-14:34) Complex Supervisor problem. DR G101400 refers.